

KING'S LYNN CONSERVANCY BOARD.



Notice to Mariners No. 11 / 2021

East Coast of England - The Wash

Approaches to King's Lynn

Removal of East Stones Light Buoy .

Mariners are advised that as a result of impact damage sustained from several vessels the East Stones Light Buoy (52° 48'.122N 00°21'.668E) has been removed from station for repairs.

Please contact the Harbour Office for further information.

27^h April 2021

P M Bailey
Deputy Harbour Master.
Harbour Office,
King's Lynn,
Norfolk PE30 ILL
T: 01553 773411
www.kingslynnport.co.uk